


# CA.SDS



**CA.SDS.02**

Sensor Box  
 Klemmkasten für Sensoren  
 Scatola Derivazione Sensori  
 Boîte de Dérivation pour Capteurs  
 Caja de Conexiones Sensores

	Power supply	INputs	OUTputs
<b>CA.SDS.02</b>	24 V dc (+/- 10%)	Maximum 2 PNP, NPN or dry contact (NO or NC) sensor switched by jumper	1 up to 2 PNP, NPN or dry contact (NO or NC) outputs switched by jumpers
<b>CA.SDS.04</b>		Maximum 4 PNP, NPN or dry contact (NO or NC) sensor switched by jumper	1 up to 4 PNP, NPN or dry contact (NO or NC) outputs switched by jumpers
<b>CA.SDS.06</b>		Maximum 6 PNP, NPN or dry contact (NO or NC) sensor switched by jumper	1 up to 6 PNP, NPN or dry contact (NO or NC) outputs switched by jumpers
<b>CA.SDS.08</b>		Maximum 8 PNP, NPN or dry contact (NO or NC) sensor switched by jumper	1 up to 8 PNP, NPN or dry contact (NO or NC) outputs switched by jumpers